
RESTORATION ITEMS



BED WOOD SILLS

The bed wood sill caps off the exposed ends of the bed wood on Ford 53-72 Short Bed Flareside (Stepside) trucks. MAR-K[™] makes bed wood kits for these years with a special indention so the bed wood sill lays flush with the wood and backs up to the bed strips, just like the original. These are also available without holes for custom applications. **MAR-K**[™] also makes Ford 51-52 Short Bed Flareside bed wood sills just like the original with their unique "U" shape. Both bed wood sills provide protection, as well as a nice appearance for the finishing touch of your Ford bed. Holes are predrilled, and bolts needed are included in your bed bolt kit.


53-72 FORD Short no holes 49"

102554	POLISHED SST	\$45.00 ea
102555	UNPOLISHED SST	40.00 ea
102556	STEEL	25.00 ea

BED SIDE WOOD FLOOR SEAL* The Box Side Wood Floor Seal for 51-72 Ford Flareside trucks is a black rubber seal made to fit between the bed side flange and the wood floor on each side. **51-72 FORD Short Flareside** 120232 SEAL......\$28.00 pr

TAILGATE BUMPER*

Made of black rubber, the Ford Tailgate Bumper fits into the ends of the tailgate for Ford Flaresides. 53-87 FORD Flareside 120231 TAILGATE BUMPER.. \$6.00 pr



WHEEL ARCH BRACE

This brace welds between the inner bedside and outer bedside skin at the wheel opening on 60-66 GM Fleetside trucks. Two braces are used on each bed side. This brace is often rusted or damaged on the original bed sides. It is made of 18 gage electrogalvanized steel and matches the shape of the original parts.

112001 BRACE \$15.00 ea



RADIATOR SUPPORT BRACKETS AND RUBBER CUSHIONS

The upper bracket (shown) and pair of lower brackets support the radiator. These fit 63-66 GM trucks to replace rusted or missing brackets. Molded rubber cushions are available to fit these brackets and support the radiator as in the original application. Installation hardware is included. Order the rubber cushions separately. Purchased from an outside vendor.

 112004
 UPPER BRACKET \$60.00 ea

 112005
 LOWER BRACKETS 27.50 pr

 112002
 UPPER CUSHION 16.00 pr

 112003
 LOWER CUSHION 15.00 pr

*Ford Tailgate Bumper and Bed Side Wood Floor Seal are both purchased from an outside vendor.



FENDER WELT

This piece of vinyl-like material fits between the fender and the bed side on Stepside trucks. It keeps the metals from scraping, and provides a seal around the fender to prevent moisture from coming through. One 30' roll is enough to do rear and front fenders. The fender welt is 1-3/4" wide with a 1/4" bead and 1/16" thick.



DOOR HINGE REPAIR PANEL

Available for 55-59 GM trucks, the door hinge repair panel is 16 gage, EDP coated and manufactured like original. The lower door hinge post is often the victim of rust. After the rusted panel is removed, this repair panel welds in place. The panel includes the "cage nuts" that are tightened after the door is secure in place. The look and fit is like new. Purchased from an outside vendor.

 100752
 DRIVER SIDE
 \$55.00 kit

 100753
 PASSENGER SIDE
 \$5.00 kit

 110683
 CAGE NUT
 6.00 ea

 (FOR REPLACEMENT)
 \$500 kit