

Rear Cross Sill Modification



The installation of a **MAR-K** steel rear pan with a license indentation usually requires modification to the rear cross sill. Since the "tag box" is indented, a space will need to be cut in the rear cross sill for clearance. The rear pan will not fit properly unless this is done.

Complete instructions are included with the rear pan, and the size and placement of the cut are included.